

100

Geoneering.com Site Development Questionnaire - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Favorites Media Print Mail

Address <http://sitedevelopment.geoneering.com/e/signup.html> Go Links

BRYANT CONSULTANTS

124 ~ [LOG IN]
126 ~ [GEONEERING HOME PAGE]

REGISTRATION

Usage of this system is restricted to those individuals and companies approved by Bryant Consultants, Inc. If you would like an account, please fill in the form below, indicate your acceptance of the User Agreement, and click "Submit".

102

Name: (First) (MI) (Last)

Company Name: 108

Address: 110

City, State, ZIP: 114

Company Web Site: http:// 116

Your Email: 118

Phone Number: 120

User Agreement: 122

Bryant Consultants, Inc., and Earthsystems Technologies are all in and of the same company. For the purposes of this User Agreement and Privacy Statement, Bryant Consultants, Inc. will represent by both entities.

Scope

This Terms of Use of Earthsystems Technologies, Inc. Content ("Agreement") is applicable to any content that is provided by Earthsystems Technologies, Inc. that you access by virtue of the Web site from which you are accessing this




FIG. 2

3/31





FIG. 3

4/31

FIG. 4



5/31

500

Geoneering.com Site Development Questionnaire - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back View Search Favorites Media Print Links

Address http://sitedevelopment.geoneering.com/e/mt_projects.html?mode=edit&projectId=56&stateinfo=eLHcEltac8bdajYq883317 Go

BRYANT
CONSULTANTS

306 ~ [PROJECT ADMIN]
308 ~ [GEONEERING]

310 ~ [CONTACT ADMIN]
312 ~ [GEONEERING OVERVIEW]
314 ~ [LOG OUT]

Project Name: Providence Phase I

Start Date: 11/12/02

End Date: ?

510 Save project

512 Back to Project Admin

514 Work with this project

502

504

506

508

Audit Info

Created: 11/12/02 11:38:30 17 - demo

Updated: -

FIG. 5

6/31

FIG. 6

600

Geoneering.com Site Development Questionnaire - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Favorites Media Print Links

Address <http://sitedevelopment.geoneering.com/e/contactadmin.html?stateInfo=eLHcEjtaC8BdaYq8833> 8

BRYANT CONSULTANTS

306 ~ [PROJECT ADMIN] 312 ~ [GEONEERING OVERVIEW]
 608 308 ~ [GEONEERING] 614 314 ~ [LOG OUT]

General Contacts Project Contacts

This is your general list of contacts. Each of these people may serve in one or more roles in any of your projects.
 Select one of your contacts to edit, or click "New" to add a new contact.

Name	Company	Email	Phone	
Bond, James	Britts Intell	jbond@007.com	555-555-5555	NEW 616
Smith, John	Smith Company	jsmith@smithco.com	555-555-5555	
Richards, Ben	Richards Engineers	brichards@richards.com	555-555-5555	
Hoffa, Jimmy	Site Concrete		555-555-5555	
Jones, Basketball	Hoop it up	bjones@hoop.net	555-555-5555	
Fraser, Dave	US Homes	dfraser@ushomes.com	555-555-5555	
Thirwell, Kevin	City of Dallas		555-555-5555	
Quest, John	Quest Engineering	jquest@quest.com	555-555-5555	
Jack, Ripper	Cutting Edge Technologies	jripper@cj.com	555-555-5555	
Tracy, Dick	Tracy Investigations	dtracy@thetracy.com	555-555-5555	602 604

7/31

700

Geoneering.com Site Development Questionnaire - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Home Search Go

Address http://sitedevelopment.geoneering.com/e/mt_clientcontacts.html?rowid=0X0000060e6&stateInfo=eLHcEjacBbdaYq8833|9

BRYANT
CONSULTANTS

Contact Administration

306 ~ [PROJECT ADMIN]
308 ~ [GEONEERING]

310 ~ [CONTACT ADMIN]
312 ~ [GEONEERING OVERVIEW]
314 ~ [LOG OUT]

Last Name: Smith 704

First Name: John 702

Company: Smith Company 706

Email: jsmith@smithco.com 708

Phone: 555-555-5555 710

712 Submit 714 Delete 716 Back to List of Contacts

Audit Info
Created: 10/31/02 11:10:37 15 -
Updated: -

FIG. 7

8/31

800

Geoneering.com Site Development Questionnaire - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Favorites Media Print Mail

Address <http://sitedevelopment.geoneering.com/e/project.html> Go Links

**B R Y A N T
CONSULTANTS**

Contact Administration 306 ~ [PROJECT ADMIN] 312 ~ [GEONEERING OVERVIEW]
 Project: Swampland Estates Phase I [!] 308 ~ [GEONEERING] 314 ~ [LOG OUT]

General Contacts **Project Contacts**

This is a list of contacts that apply to the project: "Swampland Estates Phase I"
 You should select a contact for each role. If you need to define a new contact to show up in one of the pull-down lists, click the "General Contacts" tab.

Environmental:	<input checked="" type="radio"/> Bond, James - Brits Intell	<input type="button" value="v"/>	802 ~ <input type="radio"/> Unknown for now
Civil:	<input checked="" type="radio"/> Hoffa, Jimmy - Site Concrete	<input type="button" value="v"/>	<input type="radio"/> Unknown for now
Geotechnical:	<input checked="" type="radio"/> Quest, John - Quest Engineering	<input type="button" value="v"/>	<input type="radio"/> Unknown for now
Structural:	<input checked="" type="radio"/> Ripper, Jack - Cutting Edge Technologies	<input type="button" value="v"/>	<input type="radio"/> Unknown for now
Land Developer:	<input checked="" type="radio"/> Tracy, Dick - Tracy Investigations	<input type="button" value="v"/>	<input type="radio"/> Unknown for now
Site Development:	<input checked="" type="radio"/> Smith, John - Smith Company	<input type="button" value="v"/>	<input type="radio"/> Unknown for now

814 ~

FIG. 8

9/31




FIG. 9

10/31

FIG. 10

Geoneering.com Site Development Questionnaire - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Home Search Favorites Media Print Address http://sitedevelopment.geoneering.com/e/geoneering.html?tab=Civil&stateInfo=eLHcEjtacBbdajYq8833|14 Go Links

BRYANT CONSULTANTS

Geoneering
Project: Swampland Estates Phase I [!]

306 ~ [PROJECT ADMIN] 310 ~ [CONTACT ADMIN]
312 ~ [GEONEERING OVERVIEW] 314 ~ [LOG OUT]

Risks Civil Site Development Environmental Geotechnical Structural

Have you participated in an early development, pre-construction meeting to evaluate potential civil site challenges? [More Info](#) ~ 1004

1006 ~ Yes 1008 ~ ☒ No
1010 ~ Don't know 1012 ~ ☐ Skip for now

Has the civil engineer provided positive grades on each of the building lots? [More Info](#) ~ 1004

1006 ~ ☒ Yes 1008 ~ ☐ No
1010 ~ Don't know 1012 ~ ☐ Skip for now

Has a sufficient pad design been done to avoid excessive cut and fill beneath the building pads? [More Info](#) ~ 1004

1006 ~ ☒ Yes 1008 ~ ☐ No
1010 ~ Don't know 1012 ~ ☐ Skip for now

1000

11/31




FIG. 11

12/31




FIG. 12

13/31




FIG. 13

14/31

1900

Site Administration - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Media Print Mail

Address http://sitedevelopment.geoneering.com/e/mt_settings.html?rowid=0x00005d80&stateInfo=eLHcE|acBbdajYq88833|25 Go Links

BRYANT CONSULTANTS

MAINTAIN SYSTEM SETTINGS

1908 ~ [ADMIN MAIN MENU]
1910 ~ [LOG OUT]

1912 ~ Account ID: *

1914 ~ ID Type: All

1916 ~ Setting Type: General

1918 ~ Setting Name: SessionTimeoutPeriod

1920 ~ Setting Value: 3600

1922 ~ Setting Description: Number of seconds to keep a web user's session active while waiting for a response from them. If the user simply goes away without hitting the site for too long, their session will be

1902 ~ Submit

1906 ~ Back to List of Settings

Delete 1904

Audit Info

Created: 8/17/00 15:12:45 Web User - ?

Updated: 11/04/02 12:54:34 2 -

1908 ~ [ADMIN MAIN MENU] [LOG OUT] ~ 1910

FIG. 14

15/31




FIG. 15

16/31

2100

Site Administration - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Media Print Favorites Search Address http://sitedevelopment.geoneering.com/e/mt_clients.html?rowid=0x00005de38&stateInfo=eLHcEjtacBbdajYq8833|29 Go Links

B R Y A N T
CONSULTANTS

Maintain System clients

1802 ~ [ADMIN MAIN MENU]
314 ~ [LOG OUT]

2112 ~ Client ID: 4 (Automatically assigned)
2118 ~ Client Name: Smith Company


Audit Info
Created: 10/28/02 17:06:11 2 -
Updated: -

2102 ~ Submit 2104 ~ Delete
2106 ~ Back to List of Clients 2114 ~

2108 ~ [ADMIN MAIN MENU] [LOG OUT] ~ 2110

FIG. 16

17/31



18/31

2300

Site Administration - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Home Search Favorites Media Print

Address http://sitedevelopment.geoneering.com/e/ml_siteusers.html?rowid=0X000Dec82&stateInfo=eLHcEjacBbdajYcq8833 32 Go Links

**B R Y A N T
CONSULTANTS**

Maintain System Users

1802 ~ [ADMIN MAIN MENU]
314 ~ [LOG OUT]

2332

17 (Automatically assigned)

demo (Login ID)

qhbaenldxDkMyYcj (Encoded - not actual password)

? (MM/DD/YY)

? (MM/DD/YY)

☐ (Check this box to make the user an admin user!)

8- Demo ☒ [Maintain Client List]

0 (Reset to zero if user is locked out!)

0

2314 ~ User ID:

2316 ~ User Name:

2318 ~ Password:

2320 ~ Start Date:

2322 ~ End Date:

2324 ~ Admin User:

2326 ~ Client:

2328 ~ Failure Count:

Phone:

2302 Submit 2304 Delete

2306 Back to List of Users 2312

Audit Info

Created: 11/12/02 11:05:02 5 - kzjones


Updated: 11/12/02 10:59:32 14 - mgehrig

2308 ~ [ADMIN MAIN MENU] [LOG OUT] ~ 2310

FIG. 18

19/31

FIG. 19



20/31

FIG. 20

2500

Site Administration - Microsoft Internet Explorer
File Edit View Favorites Tools Help
Back Forward Stop Search Favorites Media Print
Address http://sitedevelopment.geoneering.com/e/mt_questions.html?rowid=0X0000e0a0&stateInfo=eLHcE[taCBBda]Yq8833|36 Go Links

**B R Y A N T
CONSULTANTS**

Maintain Questions

1802 ~ [ADMIN MAIN MENU]
314 ~ [LOG OUT]

37 (Automatically assigned)
Civil [v]
0 (Within the area selected)
Have you participated in an early development, pre-construction meeting to evaluate potential civil site challenges?
 More Info
2524 2526 2528 2530
Yes: 0 No: 102 Skip: 0 DK: 103 [View Risk List...]
procs/mailto, p (User relative path)

2514 ~ Question ID:
2516 ~ Question Area:
2518 ~ Sort Order:
2520 ~ Question Text:
2522 ~ Action URL:
Risks:
2532 ~ Executable:


Audit Info
Created: 11/12/02 09:14:25 2 -
Updated: 11/12/02 09:15:40 2 -

2502 ~ Submit 2504 Delete
2506 ~ Back to List of Questions 2512

2508 ~ [ADMIN MAIN MENU] [LOG OUT] ~ 2510

21/31

FIG. 21



22/31

FIG. 22

2700

Site Administration - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Home Search Favorites Media Print Address http://sitedevelopment.geoneering.com/e/mit_risks.html?rowid=0x000051e47stateInfo=eLHcEJtacBbdaJYq8833|39 Go Links

**B R Y A N T
CONSULTANTS**

Maintain Risks

1802 ~ [ADMIN MAIN MENU]
314 ~ [LOG OUT]

2714 ~ Risk ID: 102 (Automatically assigned)

2716 ~ Risk Area: Civil ☒

2718 ~ Sort ID: 0 (Within the area selected)

2720 ~ Risk Text: Setup up a meeting with all interested parties on civil engineering site challenges

2722 ~ Action URL:

2724 ~ Distributing List: E,C,G,S,D enter role codes E,C,G,S,D

2706 ~ Submit 2708 ~ Delete

2710 ~ Back to List of Risks 2712 ~ Audit Info

Created: 10/30/02 07:39:18 2 -
Updated: 10/3 Audit fields are automatically maintained

[ADMIN MAIN MENU] [LOG OUT]

Site Administration - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Home Search Favorites Media Print Mail

Address http://sitedevelopment.geoneering.com/e/brws_contacts.html?stateInfo=eLHcejtacBbdajYq8833|41 Go Links

1802 ~ [ADMIN MAIN MENU] 314 ~ [LOG OUT]

Maintain Contacts 2808

2806 NEW 2810 FIND

Showing items 1 - 10 of 15 [Next]

ID	Client	Name	Company	Phone	Action
3	4	Smith, Steve	Acme, Inc.	555-5555-5555	
4	4	Jones, Terry	Acme, Inc. - Atlanta	555-5555-5555	
5	3	Bob, Jim	Jim Bob's Builders	555-5555-5555	
6	4	Doe, John	Smith Company	555-5555-5555	
7	4	Hiccock, Wild Bill	Freelance	555-5555-5555	
14	8	Fraser, Dave	US Homes	555-5555-5555	

2816-2818 2820 2822 2824 2812-2814

[ADMIN MAIN MENU] [LOG OUT]

2900

Site Administration - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Favorites Media Print Mail

Address http://sitedevelopment.geoneering.com/e/mt_contacts.html?rowid=0x000060e6&stateInfo=eLHcElacBbdajYq8833 | 42 Go Links

BRyant
CONSULTANTS

Maintain System Contacts

1802 ~ [ADMIN MAIN MENU]
314 ~ [LOG OUT]

16 (Automatically Assigned)

2912 ~ Contact ID:
2914 ~ Client: 8 - Demo [Maintain Client List]
2916 ~ Last Name: Smith
2918 ~ First Name: John
2920 ~ Company: Smith Consultants
2922 ~ Email: john@geoneering.com
2924 ~ Phone: 555-555-5555

2906 ~ Submit Delete 2908
2910 ~ Back to List of Contacts

Audit Info
Created: 10/31/02 11:10:37 15 -
Updated: -

2712

[ADMIN MAIN MENU] [LOG OUT]

FIG. 24

25/31

3000

Site Administration - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Favorites Media Print Links

Address http://sitedevelopment.geoneering.com/e/brws_eventlogs.html Go

BRYANT CONSULTANTS

System Events

1802 ~ [ADMIN MAIN MENU]

314 ~ [LOG OUT]

Starting: 10/27/02 3002

Ending: 11/26/02 3004

3006 ~ Show Events

ID	Date	Time	Event	User ID	Client ID
253	11/11/02	9:55:58	Login Failure: User demo1	0	0
254	11/11/02	9:56:09	Login Failure: User demo1	0	0
255	11/11/02	9:56:28	Login Failure: User demo1	0	0
256	11/11/02	9:56:39	Login Failure: User kzjones	0	0
257	11/11/02	9:56:54	Login Failure: User kzj	0	0
258	11/11/02	9:57:18	Login Failure: User kzj	0	0
259	11/11/02	9:57:54	Login Failure: User kzjones	0	0
3008	3010	3011	3012	3014	3016

FIG. 25

26/31

3100

Track User Sessions and Hits - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Favorites Media Print

Address <http://sitedevelopment.geoneering.com/e/sessmenu.html?stateInfo=eLHcEjtacBbdajYq8822> | 47 | Go | Links

BRYANT
CONSULTANTS

Session and Hit Tracking

1802 ~ [ADMIN MAIN MENU]
314 ~ [LOG OUT]

3102 ~ Choose A Report ☒

From Date:	11/26/2002	3104	End Date:	11/26/2002	3106
From Time:	00:00:00	3108	End Time:	10:57:23	3110

3112 ~ Submit Request

Notes:
 *When listing Sessions, do not request more than about a day at a time.
 **When listing Hits, do not request more than an hour or two.

[ADMIN MAIN MENU] [LOG OUT]

FIG. 26




FIG. 27

18634.0111

REPLACEMENT
SHEET

27/31

28/31

Site Administration - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Favorites Media Print View Source Go Links

Address <http://sitedevelopment.geoneering.com/e/sessiontrace.html?sessionId=eLHcEjtacBbdajYq8833&stateInfo=eLHcEjtacBbdajYq8833|59>

Hit #	Date & Time	Object Run	Query	Cookies
1	11/26/02 - 10:37:00	signup	GET:	valuedGuest = Yes 010
2	11/26/02 - 10:37:50	login	GET: stateInfo = eLHcEjtacBbdajYq8833 1	valuedGuest = Yes 010 safeSessionID = eLHcej
3	11/26/02 - 10:38:07	signup	GET:	valuedGuest = Yes 010 safeSessionID = eLHcej
4	11/26/02 - 10:38:57	login	GET: stateInfo = eLHcEjtacBbdajYq8833 3	valuedGuest = Yes 010 safeSessionID = eLHcej
5	11/26/02 - 10:39:29	login	POST: stateInfo = eLHcEjtacBbdajYq8833 4 adminuser = demo password = demo runAction = Log In	valuedGuest = Yes 010 safeSessionID = eLHcej

FIG. 28

3300




FIG. 29A




FIG. 29B




FIG. 30




FIG. 31

31/31